

GE Spring Chart

Part No.	Color	RPM Heavy	RPM Light
NA013	Brown	1620	1800
NA017	Black	1820	2100
NA020	Red	1950	2450
NA030	White	2420	2740
NA040	Blue	2530	2960
NA050	Purple	2575	3010
NA060	Green	2975	3440
NA079	Orange	3100	3660
NA086	Brown	3380	4020
NA088	Red	3530	4320

Standard Spring

GE Ultimate Spring Chart

Part No.	Color	RPM Heavy	RPM Light
NA013	Brown	1600	1800
NA017	Black	1800	2100
NA020	Red	1900	2200
NA030	White	2300	2700
NA040	Blue	2500	2900
NA050	Purple	2600	3000
NA060	Green	3000	3400
NA079	Orange	3100	3600
NA086	Brown	3400	3900
NA088	Red	3700	4300

Standard Spring

Arena Spring Chart

Part No.	Color	RPM Heavy	RPM Light
NA013	Brown	1620	1800
NA017	Black	1900	2100
NA020	Red	2040	2500
NA030	White	2470	2900
NA040	Blue	2650	3200
NA050	Purple	2900	3600
NA060	Green	3200	4000
NA079	Orange	3500	4400
NA086	Brown	3850	4900
NA088	Red	4200	5500

Standard Spring